



123 Main Street

Prepared for John Smith

Roof & chimney photoshoot

Photographic documentation


Selected exterior photographs organized for contractor review. 123 Main Street and John Smith are fictional sample details; surroundings are masked for privacy.

PHOTOSHOOT ONLY - NOT AN INSPECTION

Photography and image organization only. No condition assessment, defect identification, diagnosis, safety determination or repair recommendation is provided.

01 / MAIN ROOF OVERVIEW

SELECT A CELL TO OPEN DETAILS



A1-D2 are image-relative references. Detail views can overlap adjacent cells. Compass estimated from GPS/image alignment; not surveyed. Overview is a single photograph, not a stitched map.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street


Prepared for John Smith

Roof details / A

Reference sections A1 + A2

[BACK TO OVERVIEW](#)

A1-01 Shaded roof surface




OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Shingle courses and the visible roof transition. Visible appearance only; no condition rating or repair recommendation.

A2-01 Stepped roof transition



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Roof planes adjoining the lower-left transition. Visible appearance only; no condition rating or repair recommendation.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street


Prepared for John Smith

Roof details / B

Reference sections B1 + B2

[BACK TO OVERVIEW](#)

B1-01 Upper roof junction



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Intersecting roof surfaces near the inset roof edge. Visible appearance only; no condition rating or repair recommendation.

B2-01 Roof junction & penetration



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Roof transitions with a small pipe penetration in view. Visible appearance only; no condition rating or repair recommendation.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street

Prepared for John Smith


Roof details / C

ENLARGED VIEWS / PAGE 7

Reference sections C1 + C2

[BACK TO OVERVIEW](#)

C1-01 Upper shingle field



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Closer view of the upper roof surface and adjoining transition. Visible appearance only; no condition rating or repair recommendation.

C2-01 Circular roof fitting



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Exterior view of the circular fitting and surrounding shingles. Visible appearance only; no condition rating or repair recommendation.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street


Prepared for John Smith

Roof details / D

Reference sections D1 + D2

[BACK TO OVERVIEW](#)

D1-01 Upper outer roof edge



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Visible edge of the upper-right roof surface. Visible appearance only; no condition rating or repair recommendation.

D2-01 Outer roof surface



OVERVIEW LOCATOR

Approximate visual reference. Image may span adjoining sections.

Shingle field approaching the right-side roof edge. Visible appearance only; no condition rating or repair recommendation.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street

Prepared for John Smith

Chimney exterior

Selected views of the chimney top and exterior face. CH on the overview identifies the chimney location.

CH-01

Top and adjoining roof



CH-02

Exterior face



Captions identify photographed surfaces only. Bright reflections, shadows and viewing angle may limit detail. The images do not establish the condition of flashing, mortar, liners or concealed components.

CHIMNEY SCOPE

Exterior photo documentation only. No interior flue view, cleaning, draft testing, combustion assessment or determination of safe operation is included. A qualified chimney professional must evaluate any concerns.

OPEN ENLARGED CHIMNEY VIEWS / PAGE 8

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street

Prepared for John Smith

Roof fittings / enlarged

Enlarged crops from the original photographs. Cropping does not reveal additional detail or establish a defect.

C2-02 Circular fitting and surrounding shingles



RF-01 Small pipe penetration and adjoining roof edge



[BACK TO OVERVIEW](#)

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street

Prepared for John Smith


Chimney / enlarged

Enlarged crops from the original photographs. Cropping does not reveal additional detail or establish a defect.

CH-03 Caps, screens and visible chimney top



CH-04 Exterior surface detail



[BACK TO OVERVIEW](#)

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.



123 Main Street

Prepared for John Smith

Scope & limitations

This deliverable records an aerial photoshoot: photography and image organization only. It is not an inspection or condition assessment. These limitations apply to every image, label and page.

01 Visible exterior surfaces only

Selected camera views only. No roof access, probing, material lifting, moisture testing, thermal examination or physical testing was performed as part of this photo record.

02 No diagnosis or certification

This document does not diagnose defects, causes, leaks, structural condition, code compliance or repair needs. It is not a roof, home, engineering or chimney inspection.

03 Hidden conditions remain unknown

Decking, underlayment, framing, interiors, flue liners and other concealed components are outside scope. A photograph cannot establish watertightness, remaining life or safe operation.

04 Coverage is selective

Shadows, glare, obstructions, image resolution and camera angle limit visibility. Unpictured, masked or unmarked areas are not cleared of concerns. The sample does not document every surface.

05 Reference labels are approximate

The overview is one photograph. A1-D2 and CH are visual references, not surveyed boundaries or measurements. Compass orientation is estimated from GPS/image alignment and is not survey-verified. Detail photographs can cross section boundaries.

06 Privacy and sample status

123 Main Street and John Smith are fictional. Nonessential surroundings were cropped or masked. The delivered PDF omits original location metadata. Visible roof and chimney pixels were not retouched to change apparent condition.

07 Professional evaluation is separate

The contractor or an appropriately qualified professional should verify conditions on site and decide further inspection, testing and repair. This photo record alone is not a basis for safety, insurance, code or pricing determinations.

08 Conditions can change

Images show visible appearance at capture only. No guarantee of present or future performance, structural safety or absence of concealed issues is provided.

PHOTOSHOOT ONLY Not a roof or chimney inspection. No testing or certification.
Privacy-masked sample. Selected images do not establish complete coverage.